

State of Ohio Environmental Protection Agency

Northeast District Office 2110 E. Aurora Road Twinsburg, Ohio 44087 (216) 425-9171



Richard F. Celeste Governor

April 12, 1989

RE: OHIO EPA PERMIT NO. 3ID00021*DD NPDES PERMIT NO. 0H0004219

Mr. William Lacure
Environmental Control Coordinator
The Timken Company
1835 Dueber Avenue
Canton, Ohio 44706

Dear Mr. Lacure:

We are in receipt of your self-monitoring report covering the month of February for the referenced facility. Our review indicates violation of the conditions of your NPDES permit. The specific instance of noncompliance is as follows:

OUTFALL	DATE	PARAMETER	REPORTED	UNITS	PERMIT LIMITATION
015	2/10/89	рН	6.2	S.U.	6.5 (min)

Please be advised that failure to comply with the effluent limitations or to satisfy the monitoring or reproting requirements of your NPDES permit may be cause for enforcement action pursuant to the Ohio Revised Code Chapter 6111.

If there are any questions, please contact this office.

Sincerely,

Kelvin F. Rogers
Environmental Scientist

Division of Water Pollution Control

KFR:mjo

cc: R. Phelps, DWPC, CO